MBE/MRE / HVAC-R EXTERNAL SEALING CONNECTION TOOL

Sleeve actuated external grip and seal connection tools that latches over tube features.


CONNECTS TO:

Expanded CoreMax Seat









SPECIFICATIONS

Pressure Rating	Operating Temperatures	Materials of Construction	
Vacuum to 625 psi (43 bar)	-40°F to +250°F (-40°C to +121°C)	Stainless Steel	
Term	ination Port	Seal Material*	
1/4 to	o 1-1/4 NPT	Neoprene°	

^{*} Additional seal material types available, consult factory.

ACTUATION METHOD

Manual Sleeve: Easy, ergonomic sleeve action eliminates repetative twisting and turning - push to connect, pull to release

ICON™ TECHNOLOGY

Consult Factory

ACCESSORIES

Visit fastestinc.com

- Sleeve locks under pressure to eliminate disconnection under pressure
- MBE ball latch and MRE ring latch over tube features such as flare or bead
- 3 Straight through flow for full flow requirements
- Quick and easy seal replacement to minimize down time, maintenance, and tool inventory

MBE/MRE / HVAC-R EXTERNAL SEALING CONNECTION TOOL







	C	Dimensions				
Connects To		Replacement	Rebuild	Termination	Flow	
Tube ØX	Flare Length Y	Flare ØZ	Seals Pack (5)	Kit	Tommidation	Dia.
0.25 (6.4)	0.20 (5.1)	0.32 (8.0)	Consult Factory	Consult Factory	1/4 NPT	0.19 (4.8)
0.31 (7.9)	0.27 (6.9)	0.38 (9.7)				0.25 (6.3)
0.38 (9.7)	0.35 (8.9)	0.44 (11.3)			3/8 NPT	0.31 (7.9)
0.50 (12.7)	0.45 (11.4)	0.57 (14.5)				0.44 (11.1)
0.63 (16.0)	0.53 (13.5)	0.70 (17.8)				0.56 (14.1)
0.75 (19.1)	0.68 (17.3)	0.84 (21.3)			3/4 NPT	0.67 (16.9)
0.88 (22.4)	0.79 (20.1)	0.97 (24.6)			5/4 (VI)	0.79 (19.9)
1.00 (25.4)	0.83 (21.1)	1.12 (28.5)			1 NPT	0.94 (23.9)
1.13 (28.7)	1.13 (28.7)	1.23 (31.3)			1-1/4 NPT	1.03 (26.0)
1.38 (35.1)	1.40 (35.6)	1.49 (37.9)			1-1/4 INP 1	1.27 (32.1)

Dimensions: inch (mm)

How to Order

The MBE and MRE Series connectors are designed for mechanical gripping on expanded tubing. Connectors are designed, engineered and manufactured to your specific application requirements.

For part number and a price quotation:

- 1) Identify the gripping and sealing areas of your test piece.
- 2) Contact FasTest with information on test pressure, media and provide detailed drawing, including tolerances of test piece.